

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Autocruise Wentworth
Reg Number - NO GAP	YN07GDE
HPI Clear	Yes
VAT	No
Engine Size	3.0
BHP	160
Transmission	Manual
Vehicle Weight (kg)	4000
Miles or KM	Miles
Mileage	31626
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Bike Rack, Electric step, Habitation door lock, Reversing camera, Solar panel, Tow bar, Tv Aerial
Other External Extras	
Decals	Need attention
Decals Further Info	Faded and Some replaced over the old ones



Any Damage Found	Yes
Damage Further Info	Faded headlights // Delaminated badge // Faded paintwork on front bumper // Scuff on n/s front bumper // Scuff to wheel arch o/s/f // Paint fallout on a pillar // Rust on o/s/r corner // Scratch on o/s/r pillar // Tow bar rusty // Outside habitation lock damage // Scratches down the n/s



Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	Not Working
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection






Internal Extras	cab A/C, Cab blinds, Alarm, Other (inc accessories), Multifunction steering wheel, Oven, Cruise control
Other Extras	Immobilisor Microwave
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	No
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Under n/s bench seats showing high floor added tiles // Not original glass



Damp Inspection

Damp (visible/soft)	Yes
---------------------	-----

Damp Info	Dry rot under floor under cooker
Floor damp/spongy/damaged	Yes
Floor Info	Dry rot under floor in rear and down the sides




CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	2 services last one photographed
Date of Last Engine Service	04/06/2014
Cam belt changed	N/A
Habitation service reports	Partial
Habitation Info	One report photographed
Date of Last Habitation Service	16/09/2015



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	Yes
Engine Lights Info	Bulb out light showing
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Arran Ashman
Sign-off Date	2026-09-18