CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Elddis Autoquest 155
Reg Number - NO GAP	BX68JHK
HPI Clear	Yes
VAT	Yes
Engine Size	2.0
BHP	130
Transmission	Manual
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	13770
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes
MOT Expiry Date	27/03/27
Vehicle Registration Date	01/11/18

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

Date Submitted: 10/11/2026 08:56 AM
Submitted By: Tim Craner

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Bench Seats, French Bed
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

Date Submitted: 10/11/2026 08:56 AM
Submitted By: Tim Craner

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Reversing camera, Bike Rack, Satellite dome, Tv Aerial, Awning
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Repair to n/s rear bumper corner// dent to rear o/s/r top corner//





Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

Date Submitted: 10/11/2026 08:56 AM
Submitted By: Tim Craner

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Cab blinds, Cruise control, DAB radio, Heated mirrors, Multifunction steering wheel, Oven, Tv(s), Carpets
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	No

Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Water mark to n/s front //
Floor damp/spongy/damaged	No





CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 10/11/2026 08:56 AM
Submitted By: Tim Craner

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes



Engine Service History	Partial
Service Info	2022-2026 paper invoice and stamps
Date of Last Engine Service	25/02/26
Cam belt changed	No
Habitation service reports	Partial
Habitation Info	2021 and 2026
Date of Last Habitation Service	31-1-26









Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Rodger Snell
Sign-off Date	2026-11-10