Date Submitted: 29/10/2026 09:54 AM
Submitted By: David Walker

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Auto-Sleepers Mezan Low Line
Reg Number - NO GAP	CN09CME
HPI Clear	Yes
VAT	No
Engine Size	1.6
BHP	88
Transmission	Manual
Vehicle Weight (kg)	1930
Miles or KM	Miles
Mileage	69914
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes
MOT Expiry Date	
Vehicle Registration Date	25/03/2009

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

Date Submitted: 29/10/2026 09:54 AM
Submitted By: David Walker

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 29/10/2026 09:54 AM
Submitted By: David Walker

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Front fog lights, Parking sensors, Roof rack, Habitation door lock
Other External Extras	N/A
Decals	Need attention
Decals Further Info	Cracking on door // missing on front roof //





Any Damage Found	Yes
Damage Further Info	Rust and chip on bonnet // painted rear bumper coming off // replacement window in rear door // dent on drivers door







Windscreen	

Chip(s) smaller than 10p	



Alloy Wheels	Need attention
Alloy Further Info	Flaking and scratched







Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	No

Date Submitted: 29/10/2026 09:54 AM
Submitted By: David Walker

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	cab A/C, Cab curtains, Oven
Other Extras	N/A
Electrics turn on	No
More Info	Leisure battery not connected
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	No
Internal Damage	Yes
Damage Info	Damage around rear door



Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 29/10/2026 09:54 AM
Submitted By: David Walker

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes



Engine Service History	Partial
Service Info	Invoiced and three stamps
Date of Last Engine Service	19/08/2022
Cam belt changed	No
Habitation service reports	None





Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	Yes
V5 tested on DVLA	Yes
Completed by	David Walker
Sign-off Date	2026-10-29