Date Submitted: 16/11/2026 13:16 PM
Submitted By: Jonathan Hayreh

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Auto-Trail Apache 600 SE
Reg Number - NO GAP	DX06XSW
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	110
Transmission	Manual
Vehicle Weight (kg)	3400
Miles or KM	Miles
Mileage	48464
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes
MOT Expiry Date	14/07/2027
Vehicle Registration Date	01/03/2006

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

Date Submitted: 16/11/2026 13:16 PM
Submitted By: Jonathan Hayreh

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	N/A
Clutch Slip Test Pass	N/A
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Bench Seats, Overcab Bed
Lounge Layout	Full Dinette
Layout Correct	Yes
Further Comments	N/A

CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 16/11/2026 13:16 PM
Submitted By: Jonathan Hayreh

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Air Suspension, Awning, Bike Rack, Electric step, Front fog lights, Habitation door lock, Ladder, Tv Aerial, Reversing camera, BBQ point
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Paint peel from offside wing & door edge// Sticker covering small dent rear nearside// Reversing lights not working.// Cracks to front of gas locker door frame & door will not secure. Held by tape// Rear nearside wheel trim missing. Other wheeltrims are odd//











Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	Yes
Tyre Further Info	Front tyres are 2023 & in good condition. Rear offside is new 2026 Rear nearside has no date. Tyre looks ok but steel wheel is excessively rusted





Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 16/11/2026 13:16 PM
Submitted By: Jonathan Hayreh

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Awning (Porch or Safari), Cab blinds, Cab curtains, Oven
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Hab door blind broken// Marks to worktop// Slight vinyl peel on overcab above ladder fixing//poor repair to shower tray









Damp Inspection

Damp (visible/soft)	Yes

Damp Info	Roof above middle offside locker read 100% & blue staining// Ceiling in middle nearside locker 100%// Ceiling across full width between 2 above// Wall above floor immediately behind passenger seat// Wall above floor immediately behind drivers seat
Floor damp/spongy/damaged	No








CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 16/11/2026 13:16 PM
Submitted By: Jonathan Hayreh

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes



Engine Service History	Partial
Service Info	Invoices for 2007, 2017 2018 2021 2023,2024,2025
Date of Last Engine Service	14/08/2025
Cam belt changed	No
Habitation service reports	None















Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	N/A
V5 tested on DVLA	Yes
Completed by	Tim Craner
Sign-off Date	2026-11-16