Date Submitted: 11/11/2026 06:00 AM
Submitted By: Arran Ashman

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Elddis Encore 250
Reg Number - NO GAP	FJ21BVM
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	140
Transmission	Automatic
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	6328
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes
MOT Expiry Date	18/06/2027
Vehicle Registration Date	28/04/2021

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

Date Submitted: 11/11/2026 06:00 AM
Submitted By: Arran Ashman

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	No
Notes	Missing a seat
Berths	3
Belts	3
Bed Options	French Bed, Bench Seats
Lounge Layout	Bench Seats
Layout Correct	No
Further Comments	N/A





Date Submitted: 11/11/2026 06:00 AM
Submitted By: Arran Ashman

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Tv Aerial, Reversing camera, Solar panel, Alloys
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Cracked rear bumper been repaired. Couple of stone chips





Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 11/11/2026 06:00 AM
Submitted By: Arran Ashman

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	tracker, Carpets, Cab blinds, cab A/C, Bluetooth, Cruise control, DAB radio, Heated mirrors, Multifunction steering wheel, Oven, Other (inc accessories)
Other Extras	Microwave
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Shelves added in lounge area Mattress slightly fraud along the join Fridge door missing plastic insert so comes away when you open it.







Damp Inspection

Damp (visible/soft)	Yes

Damp Info	High reading under bench
Floor damp/spongy/damaged	No



CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 11/11/2026 06:00 AM
Submitted By: Arran Ashman

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	No
Engine Service History	Partial
Service Info	1 invoice
Date of Last Engine Service	12/07/2022
Cam belt changed	No
Habitation service reports	Partial
Habitation Info	3 invoices
Date of Last Habitation Service	19/06/2026


E S Hartley Limited
Motorhome Service Checksheet


Motorhome Annual Habitation Service Check Sheet

Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Arran Ashman

Sign-off Date	2026-11-11