Date Submitted: 13/11/2026 09:19 AM
Submitted By: Keenan Parnell

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Swift Voyager 574
Reg Number - NO GAP	FY26AZU
HPI Clear	Yes
VAT	No
Engine Size	2.0L
BHP	150 BHP
Transmission	Automatic
Vehicle Weight (kg)	3550kg
Miles or KM	Miles
Mileage	1836 miles
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes
MOT Expiry Date	01-03-2029
Vehicle Registration Date	05-03-2026

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

Date Submitted: 13/11/2026 09:19 AM
Submitted By: Keenan Parnell

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	N/A
Clutch Slip Test Pass	N/A
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	6
Belts	4
Bed Options	Drop Down Bed, Bench Seats
Lounge Layout	Full Dinette
Layout Correct	Yes
Further Comments	N/A

Date Submitted: 13/11/2026 09:19 AM
Submitted By: Keenan Parnell

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Awning, Gaslow, Solar panel, Front fog lights, Reversing camera, Shower point, BBQ point, LED daytime running lights, Parking sensors
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Off side rear corner damage





Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

Date Submitted: 13/11/2026 09:19 AM
Submitted By: Keenan Parnell

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Bluetooth, cab A/C, Cab blinds, Carpets, Cruise control, DAB radio, Diesel heater, Multifunction steering wheel, Oven, Sat nav, Climate control, Auto headlights
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	No

Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes



Engine Service History	None
Cam belt changed	No
Habitation service reports	None

Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	Yes
Engine Lights Info	Service light on
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Alan Wileman
Sign-off Date	2026-11-13