Date Submitted: 09/10/2026 08:33 AM
Submitted By: Keenan Parnell

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Bus stop VW Conversions
Reg Number - NO GAP	GL04OWE,GD67XYN
HPI Clear	Yes
VAT	No
Engine Size	2.0L
BHP	130bhp
Transmission	Manual
Vehicle Weight (kg)	3000kg
Miles or KM	Miles
Mileage	50406
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes
MOT Expiry Date	
Vehicle Registration Date	

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

Date Submitted: 09/10/2026 08:33 AM
Submitted By: Keenan Parnell

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	7
Bed Options	Campervan, Bench Seats
Lounge Layout	Bench Seats, Two Forward Facing
Layout Correct	Yes
Further Comments	N/A

CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 09/10/2026 08:33 AM
Submitted By: Keenan Parnell

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Front fog lights, Reversing camera, Solar panel, Roof rack
Other External Extras	N/A
Decals	N/A
Any Damage Found	Yes
Damage Further Info	Paint peel on passenger door edge just starting to rust Small dink on rear door Small dink on passenger door as described by customer Rust near near side wheel Arch Front bumper been repaired slightly different colour and some crazing Rust starting to show on off side rear wheel arch Scratch on rear bumper (top)











Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	Yes
Pop Top Damage Info	Small holes os rear pop top //



Date Submitted: 09/10/2026 08:33 AM
Submitted By: Keenan Parnell

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Bluetooth, cab A/C, DAB radio, Cruise control, Multifunction steering wheel, Part leather
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Slighty stained upholstery //



Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 09/10/2026 08:33 AM
Submitted By: Keenan Parnell

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes



Engine Service History	Partial
Service Info	Two services present Last one pictured
Date of Last Engine Service	05/02/2025
Cam belt changed	Yes
Cam belt info	Changed in feb 2025
Habitation service reports	None



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Alan Wileman

Sign-off Date	2026-10-09