Date Submitted: 17/11/2026 09:56 AM
Submitted By: Bob Smith

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Swift Bessacarr E540
Reg Number - NO GAP	HX07HMA
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	130
Transmission	Manual
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	34012
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	1
V5 present	Yes
V5 VIN Match	Yes
MOT Expiry Date	15/05/27
Vehicle Registration Date	03/05/07

Engine Bay

Fluid levels correct?	No
More Info	Coolant a little below minimum
Oil/Coolant Contamination	No
Engine bay check	Pass

Date Submitted: 17/11/2026 09:56 AM
Submitted By: Bob Smith

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 17/11/2026 09:56 AM
Submitted By: Bob Smith


CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Gaslow, Reversing camera, Tv Aerial, Bike Rack, Solar panel
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Peeling paint to bonnet // Scratch to front valance // Crack o/s indicator lense // Peeling paint drivers door // Broken piece off gas locker door // Scuffs to o/s valance // Cracks to r/o/s corner valance // Scuffs to n/s // N/s/r wheel arch broken // Headlamps discoloured //



















Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	Yes
Tyre Further Info	R/n/s old and perished and cracked



Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 17/11/2026 09:56 AM
Submitted By: Bob Smith


CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Alarm, Bluetooth, Cab blinds, Cruise control, Oven, Tv(s)
Other Extras	2000w inverter
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	No
Internal Damage	Yes
Damage Info	Overcab skylight cracked at several points// Flip down cab tv missing // All cab surfaces with damp/mould discolouration // Scratch to kitchen cabinet // Bench cushions mouldy //












Damp Inspection

Damp (visible/soft)	Yes
Damp Info	O/s cupboard above bench mould // Rippled paper beneath o/s hab window // Mould under o/s bench seat // Rippled wall beneath n/s hab window // Wet very soft wall beneath n/s bench & locker door // Around hab door rippled // Rear wall below bathroom window rippled and soft //
Floor damp/spongy/damaged	No
















CMS
AUCTIONS
Browse | Bid | Buy


Date Submitted: 17/11/2026 09:56 AM
Submitted By: Bob Smith


CMS MOTORHOME INSPECTION FORM


Paperwork

Manuals present	No
Engine Service History	Partial
Service Info	2/7/09 // 16/5/11 // 12/2/13 // 31/3:14 // 8/3/15 // 10/3/16 ……. All stamps 28/3/22 // 16/5/25 // …. Invoices
Date of Last Engine Service	16/05/25
Cam belt changed	Yes
Cam belt info	01/05/26
Habitation service reports	Partial
Habitation Info	June 2008 July 2011 Feb 2013 March 2015
Date of Last Habitation Service	16/03/2015









Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	Yes
Engine Lights Info	EML diagnosed as egr valve
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Bob Smith
Sign-off Date	2026-11-17