Date Submitted: 04/11/2026 09:39 AM
Submitted By: Keenan Parnell

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Auto - Trail Cheyenne 630 SE
Reg Number - NO GAP	KN03LOH
HPI Clear	Yes
VAT	No
Engine Size	2.7
BHP	155
Transmission	Automatic
Vehicle Weight (kg)	3800
Miles or KM	Miles
Mileage	51644
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes
MOT Expiry Date	25/06/2027
Vehicle Registration Date	29/05/2003

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

Date Submitted: 04/11/2026 09:39 AM
Submitted By: Keenan Parnell

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	N/A
Clutch Slip Test Pass	N/A
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 04/11/2026 09:39 AM
Submitted By: Keenan Parnell

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Electric step, Habitation door lock, BBQ point, Tow bar, Gaslow, Solar panel, Tv Aerial, Air Suspension
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Rusting drivers door // scuff os front window // crazing os rear bumper // bubbling nsr wheel arch // rusting passenger door //













Windscreen	No damage

Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 04/11/2026 09:39 AM
Submitted By: Keenan Parnell

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Oven, Carpets, Cab curtains, Cruise control
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	No

Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Blue under ns front window // blue under nsr wheel arch // blue in rear panel all reading highs
Floor damp/spongy/damaged	No









CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 04/11/2026 09:39 AM
Submitted By: Keenan Parnell

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes



Engine Service History	Partial
Service Info	3 stamps 3 invoices
Date of Last Engine Service	14/10/2015
Cam belt changed	N/A
Habitation service reports	Partial
Habitation Info	2 invoices
Date of Last Habitation Service	10/09/2020





Test Drive & Sign Off

Test drive - 10 mins	Fail
Test Drive Details	Limp mode
Engine lights	Yes
Engine Lights Info	Edc light abs light and another light
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Keenan Parnell
Sign-off Date	2026-11-04