Date Submitted: 18/11/2026 10:35 AM
Submitted By: Bob Smith

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Elddis Majestic 120
Reg Number - NO GAP	PO18HRE
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	130
Transmission	Manual
Vehicle Weight (kg)	3300
Miles or KM	Miles
Mileage	20052
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes
MOT Expiry Date	04/08/27
Vehicle Registration Date	15/08/18

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

Date Submitted: 18/11/2026 10:35 AM
Submitted By: Bob Smith

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	U Shape Rear
Lounge Layout	U-Shaped Rear Lounge
Layout Correct	Yes
Further Comments	N/A

CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 18/11/2026 10:35 AM
Submitted By: Bob Smith

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Awning, Gaslow, Solar panel, Tow bar, Tv Aerial, Reversing camera
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	brush scratches to n/s // dent in rear under window//







Windscreen	No damage
Alloy Wheels	Need attention
Alloy Further Info	N/s front scratched



Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

Date Submitted: 18/11/2026 10:35 AM
Submitted By: Bob Smith

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	cab A/C, Cab blinds, Carpets, Cruise control, Heated mirrors, Multifunction steering wheel, Oven, Sat nav
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	No

Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Rear sky light blue stains //
Floor damp/spongy/damaged	No




CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 18/11/2026 10:35 AM
Submitted By: Bob Smith


CMS MOTORHOME INSPECTION FORM


Paperwork


Manuals present	Yes




Engine Service History	Partial
Service Info	2020-2025 4 stamps and paper work
Date of Last Engine Service	16-07-2025
Cam belt changed	No
Habitation service reports	Full
Habitation Info	2019-2026
Date of Last Habitation Service	25/ aug/ 26









Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Rodger Snell
Sign-off Date	2026-11-18