Date Submitted: 29/10/2026 08:58 AM
Submitted By: Alan Wileman

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Burstner Argos A747-2
Reg Number - NO GAP	PX05MHZ
HPI Clear	Yes
VAT	No
Engine Size	2.8L
BHP	130 bhp
Transmission	Manual
Vehicle Weight (kg)	5000kg
Miles or KM	Miles
Mileage	52095
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes
MOT Expiry Date	06-01-2027
Vehicle Registration Date	25-07-2005

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

Date Submitted: 29/10/2026 08:58 AM
Submitted By: Alan Wileman

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	6
Belts	6
Bed Options	Overcab Bed, Transverse Bed, Bench Seats
Lounge Layout	Full Dinette
Layout Correct	Yes
Further Comments	N/A

CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 29/10/2026 08:58 AM
Submitted By: Alan Wileman

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Electric step, Habitation door lock
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Dents and scuffs all over body work Hab door panel instead of windows











Windscreen	No damage
Alloy Wheels	

N/A	
Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	No
Pop top canvas damage	N/A

CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 29/10/2026 08:58 AM
Submitted By: Alan Wileman

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Cab curtains, Leather, Upgraded stereo
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Edge of bench seats frayed Hab door lock mounting crudely put in





Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Garage rear wall rotting
Floor damp/spongy/damaged	No



CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 29/10/2026 08:58 AM
Submitted By: Alan Wileman

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	N/A
Date of Last Engine Service	24-12-2025
Cam belt changed	Yes
Cam belt info	Changed 2016
Habitation service reports	Partial
Habitation Info	Four invoices
Date of Last Habitation Service	2006





Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes

Completed by	Alan Wileman
Sign-off Date	2026-10-29