Date Submitted: 12/11/2026 09:23 AM
Submitted By: Alan Wileman

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Auto-sleepers Duetto
Reg Number - NO GAP	RRR239R
HPI Clear	Yes
VAT	No
Engine Size	2.4L
BHP	100 bhp
Transmission	Automatic
Vehicle Weight (kg)	3280
Miles or KM	Miles
Mileage	38224
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes
MOT Expiry Date	01/12/2026
Vehicle Registration Date	22/04-2004

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

Date Submitted: 12/11/2026 09:23 AM
Submitted By: Alan Wileman

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	N/A
Clutch Slip Test Pass	N/A
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 12/11/2026 09:23 AM
Submitted By: Alan Wileman

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Bike Rack, Manual step, Solar panel
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Rust spots above passenger door Chip on passenger door Nearside window rubber perished Scratch above hab window near side Scratch /dent along top panel rear off side







Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	Yes
Tyre Further Info	Tyres 2017 but in reasonable condition



Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

Date Submitted: 12/11/2026 09:23 AM
Submitted By: Alan Wileman

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Cab curtains, Carpets, Multifunction steering wheel, Oven, Part leather
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	N/A
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Window in wash room cracked



Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Over cab area high readings Near side Higher readings under near side bench seat on floor Higher readings under cooker / sink on floor
Floor damp/spongy/damaged	No

CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 12/11/2026 09:23 AM
Submitted By: Alan Wileman

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Full
Service Info	All Invoices present all 20 years Latest pictured
Date of Last Engine Service	30/05/2025
Cam belt changed	Yes
Cam belt info	Changed 2009
Habitation service reports	None





Test Drive & Sign Off

Test drive - 10 mins	Pass

2026-11-12