Date Submitted: 12/10/2026 09:46 AM
Submitted By: Tim Craner

# CMS MOTORHOME INSPECTION FORM

## General Information

| | |
|---|---|
| Make & Model | Leisuredrive Celebration |
| Reg Number - NO GAP | SG10ADS |
| HPI Clear | Yes |
| VAT | No |
| Engine Size | 2.3 |
| BHP | 130 |
| Transmission | Automatic |
| Vehicle Weight (kg) | 3000 |
| Miles or KM | Miles |
| Mileage | 31561 |
| Confirm miles (within 5,000) | Yes |
| Is Mileage Warranted | Yes |
| Engine Keys Count | 2 |
| V5 present | Yes |
| V5 VIN Match | Yes |
| MOT Expiry Date | |
| Vehicle Registration Date | |

## Engine Bay

| | |
|---|---|
| Fluid levels correct? | Yes |
| Oil/Coolant Contamination | No |
| Engine bay check | Pass |

Date Submitted: 12/10/2026 09:46 AM
Submitted By: Tim Craner

# CMS MOTORHOME INSPECTION FORM

## Mechanical Inspection

| | |
|---|---|
| Brake Pedal Pressure Pass | Yes |
| Handbrake Test Pass | Yes |
| Static Gear Selection Pass | N/A |
| Clutch Slip Test Pass | Yes |
| Steering Noise | No |
| Engine Noise | No |

## Internal Layout

| | |
|---|---|
| Does internal look original? | Yes |
| Berths | 2 |
| Belts | 3 |
| Bed Options | Campervan |
| Lounge Layout | Bench Seats |
| Layout Correct | Yes |
| Further Comments | N/A |

**CMS**
AUCTIONS
Browse | Bid | Buy

Date Submitted: 12/10/2026 09:46 AM
Submitted By: Tim Craner

# CMS MOTORHOME INSPECTION FORM

## Exterior Inspection

| | |
|---|---|
| External Extras | Electric step, Reversing camera, Parking sensors, Tv Aerial |
| Other External Extras | N/A |
| Decals | Good |
| Any Damage Found | Yes |
| Damage Further Info | Paint peel n/s above side door<br>Scratch above n/s/r wheel arch<br>Paint peel on n/s hab door handle |













| | |
|---|---|
| Windscreen | Chip(s) smaller than 10p |



| | |
|---|---|
| Alloy Wheels | Good |
| Tyres illegal/cracking/out of date | No |
| Electric Step | Fully Working |
| Self levelling work | N/A |
| Pop top canvas damage | N/A |

**CMS**
AUCTIONS
Browse | Bid | Buy

Date Submitted: 12/10/2026 09:46 AM
Submitted By: Tim Craner

# CMS MOTORHOME INSPECTION FORM

## Internal Inspection

| | |
|---|---|
| Internal Extras | Cab curtains, Cruise control, Diesel heater, Leather, Multifunction steering wheel, Tv(s), Climate control |
| Other Extras | N/A |
| Electrics turn on | Yes |
| Control panel damaged | No |
| Stereo turn on | Yes |
| Smell or signs of smoking | No |
| Cushions correct | Yes |
| Boiler present | N/A |
| Overhead lockers ready | Yes |
| Internal Damage | Yes |
| Damage Info | Discolouration of plastic trim o/s door pillar rear edge<br>Screw holes lower cupboard door<br>Rear panel cracked (view from rear doors ) |







## Damp Inspection

| | |
|---|---|
| Damp (visible/soft) | |

| | |
|---|---|
| No | |
| Floor damp/spongy/damaged | No |

# CMS MOTORHOME INSPECTION FORM

## Paperwork

| | |
|---|---|
| Manuals present | Yes |




| | |
|---|---|
| Engine Service History | None |
| Cam belt changed | No |
| Habitation service reports | None |

## Test Drive & Sign Off

| | |
|---|---|
| Test drive - 10 mins | Pass |
| Engine lights | No |
| Dashboard ghosting/Mileage flashing | Yes |
| V5 tested on DVLA | Yes |
| Completed by | Bob Smith |
| Sign-off Date | 2026-10-12 |