

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Bilbo's Celex
Reg Number - NO GAP	JR04AYR
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	180
Transmission	Automatic
Vehicle Weight (kg)	3000
Miles or KM	Miles
Mileage	36223
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	N/A
Clutch Slip Test Pass	N/A
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	2
Belts	4
Bed Options	Campervan
Lounge Layout	Two Forward Facing
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Parking sensors, Tow bar, Front fog lights
Other External Extras	N/A
Decals	N/A
Any Damage Found	Yes
Damage Further Info	Corrosion rust above windscreen Scratch drivers door Rusting top o/s A pillar Damage to o/s edge of high top





Windscreen	No damage
Alloy Wheels	Need attention
Alloy Further Info	Both rear alloys bubbling



Tyres illegal/cracking/out of date	No
------------------------------------	----

Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Bluetooth, cab A/C, Carpets, DAB radio, Diesel heater, Draw locking, Heated mirrors, Leather, Multifunction steering wheel, Sat nav, Traction control plus, Cab curtains
Other Extras	Water fill point rear locker (internal) External shower from internal rear locker Small grill fitted
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Both internal front door open handles degraded and discoloured Scratch to table top Fridge door catch broken



Damp Inspection

Damp (visible/soft)	
---------------------	--

No	
Floor damp/spongy/damaged	No


CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	23/10/2012, 03/10/2022, 30/09/2024, 13/06/2025, 01/06/2026 Engine change 20/01/2025
Date of Last Engine Service	01/06/2026
Cam belt changed	Yes
Cam belt info	At engineer change 20/01/2025
Habitation service reports	None



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Bob Smith
Sign-off Date	2026-08-20