

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Rimor seal 69p plus
Reg Number - NO GAP	YX19BYL
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	130
Transmission	Automatic
Vehicle Weight (kg)	3650
Miles or KM	Miles
Mileage	11240
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	N/A
Clutch Slip Test Pass	N/A
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	5
Belts	5
Bed Options	Drop Down Bed, Island Bed, Bench Seats
Lounge Layout	Bench Seats, Two Forward Facing
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Reversing camera, Bike Rack, Tv Aerial
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Damage to o/s wing mirror// poor seal repair to o/s over cab and on NS lower trim.// door stay missing //n/s/r locker has delaminate





Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection


Internal Extras	Cab curtains, Cruise control, cab A/C, Oven, Bluetooth
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Roof over drop down bed damage // seating cushions flat // floor cab to hab trim coming away



Damp Inspection

Damp (visible/soft)	Yes
---------------------	-----

Floor damp/spongy/damaged	No




CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	X2 stamps in book and one invoice
Date of Last Engine Service	30/04/25
Cam belt changed	No
Habitation service reports	Partial
Habitation Info	13/5/21
Date of Last Habitation Service	13/5/21



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Rodger Snell
Sign-off Date	2026-09-14