

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Chausson Flash 14
Reg Number - NO GAP	HX11EFJ
HPI Clear	Yes
VAT	No
Engine Size	2200 cc
BHP	90 bhp
Transmission	Manual
Vehicle Weight (kg)	3500 kg
Miles or KM	Miles
Mileage	72749
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	3
Belts	4
Bed Options	Bench Seats, Twin Beds Over Garage
Lounge Layout	Full Dinette
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Tow bar, Reversing camera
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Damage to hab door (two dents) Poor sealant around air vents off Side Off side garage door sealed shut Damage to rear bumper off side near light cluster Quite serious damage to rear near side near light cluster Near side garage door poor Fit





Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A


CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	cab A/C, Cab curtains, Cruise control, Multifunction steering wheel, Tv(s)
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	N/A

Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Garage floor soft in near side rear corner Back wall of garage high readings Border laminating under shower High readings on floor in cupboard under grill
Floor damp/spongy/damaged	Yes
Floor Info	Garage floor soft in near side rear corner







CMS MOTORHOME INSPECTION FORM


Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Full
Service Info	All Services present Last one pictured
Date of Last Engine Service	31/07/2026
Cam belt changed	N/A
Habitation service reports	Partial
Habitation Info	One service
Date of Last Habitation Service	10/04/2016





Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	N/A
V5 tested on DVLA	Yes
Completed by	Alan Wileman
Sign-off Date	2026-09-14