Date Submitted: 06/11/2026 10:14 AM
Submitted By: Tim Craner

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Bailey Adamo 69-4
Reg Number - NO GAP	KX23ADO
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	160
Transmission	Automatic
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	9181
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes
MOT Expiry Date	28/02/2027
Vehicle Registration Date	01/03/2023

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

Date Submitted: 06/11/2026 10:14 AM
Submitted By: Tim Craner

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Bench Seats, Drop Down Bed
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

Date Submitted: 06/11/2026 10:14 AM
Submitted By: Tim Craner

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Awning, Bike Rack, Front fog lights, Reversing camera, Shower point, Solar panel, Tv Aerial
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Nearside upper marker light lens missing. Light works



Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

Date Submitted: 06/11/2026 10:14 AM
Submitted By: Tim Craner

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Auto headlights, Bluetooth, cab A/C, Cab blinds, Carpets, Cruise control, DAB radio, Multifunction steering wheel, Oven, Other (inc accessories)
Other Extras	Electric table height adjustment
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	No

Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 06/11/2026 10:14 AM
Submitted By: Tim Craner

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes



Engine Service History	Full
Service Info	08/02/2024
Date of Last Engine Service	08/02/24
Cam belt changed	N/A
Habitation service reports	Partial
Habitation Info	03/03/2023
Date of Last Habitation Service	03/03/2023





Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Bob Smith
Sign-off Date	2026-11-06