

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Swift Suntor 530LP
Reg Number - NO GAP	BX55EWJ
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	84
Transmission	Manual
Vehicle Weight (kg)	3000
Miles or KM	Miles
Mileage	32796
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection


External Extras	Alloys, Awning, Bike Rack, Electric step, Habitation door lock, Ladder, Tv Aerial, Roof rack
Other External Extras	N/A
Decals	Need attention
Decals Further Info	Faded all present



Any Damage Found	Yes
Damage Further Info	Front n/s small scratch//silicone missing front o/s door//small crack off side rear wheel arch cover//slight scratching front l/window//rear o/s quarter small crack//upper cab area above driver brush marks//tiny dent above rear wheel towards back//nearside front window scratching//above passenger door silicone missing//n/s trim short behind door//



Windscreen	No damage
Alloy Wheels	Need attention
Alloy Further Info	Front nearside slight peel//other all ok




Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Bluetooth, Cab curtains, Carpets, Oven, Upgraded stereo, DAB radio
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Nearside bench street repair//offside bench seat repair




Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
	
	

Engine Service History	Partial
Service Info	19/9/2025
Date of Last Engine Service	19/9/2025
Cam belt changed	No
Habitation service reports	Partial
Habitation Info	Partial
Date of Last Habitation Service	20/10/2005

	
---	--



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Mark Czechowski
Sign-off Date	2026-09-14