

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Swift Rio 325
Reg Number - NO GAP	MX65FXM
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	150
Transmission	Manual
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	38290
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No



Internal Layout

Does internal look original?	Yes
Berths	2
Belts	4
Bed Options	Transverse Bed, Bench Seats
Lounge Layout	Two Forward Facing
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Bike Rack, BBQ point, LED daytime running lights, Parking sensors, Reversing camera, Shower point, Tv Aerial, Solar panel
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Stone chips to bonnet // Branches scuff mid n/s high // Hab door glass cracked



Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Bluetooth, cab A/C, Cab blinds, Carpets, DAB radio, Cruise control, Oven
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Material dressing panels both sides of rear bed stained




Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM


Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	09/01/2018 book stamp Mileage 17285 (no date) book stamp 27/06/2023 full service 24/07/2024 full service
Date of Last Engine Service	24/07/2024
Cam belt changed	Yes
Cam belt info	07/07/2023 belt, tensioner & waterpump
Habitation service reports	Partial
Habitation Info	14/09/2020
Date of Last Habitation Service	14/09/2020





Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Bob Smith
Sign-off Date	2026-09-14