

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Auto-Sleepers Broadway EK
Reg Number - NO GAP	PO16DDZ
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	159
Transmission	Manual
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	35446
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Bench Seats, Overcab Bed
Lounge Layout	Bench Seats, Full Dinette
Layout Correct	Yes
Further Comments	N/A



CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Awning, Electric step, Front fog lights, Habitation door lock, Reversing camera, Tv Aerial, Gaslow, LED daytime running lights
Other External Extras	N/A
Decals	Need attention
Decals Further Info	Faded on o/s // Slight scuff n/s



Any Damage Found	Yes
Damage Further Info	Small scratch where wipers have caught the side // Scuff to rear of o/s bumper // Mark to rear bumper





Windscreen	Chip(s) smaller than 10p
------------	--------------------------




Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM


Internal Inspection

Internal Extras	Alarm, cab A/C, Cab blinds, Cruise control, DAB radio, Heated mirrors, Multifunction steering wheel, Oven, Part leather, Other (inc accessories), Bluetooth
Other Extras	Microwave
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Drivers seat



Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Blue staining next to habitation door
Floor damp/spongy/damaged	No




CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	3 stamps latest pictured
Date of Last Engine Service	19/11/2024
Cam belt changed	N/A
Habitation service reports	Partial
Habitation Info	3 latest pictured
Date of Last Habitation Service	15/08/2022



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Arran Ashman
Sign-off Date	2026-09-17