

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Citreon Relay
Reg Number - NO GAP	PJ65NYZ
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	130
Transmission	Manual
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	98817
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No




Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A






CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Parking sensors, Solar panel, Tv Aerial
Other External Extras	N/A
Decals	Need attention
Decals Further Info	Cracked o/s & n/s



Any Damage Found	Yes
Damage Further Info	Stone chips on bonnet 1-10 // rusting on o/s seam // paint flake on rear bumper //




Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Bluetooth, Multifunction steering wheel, tracker, Cruise control, cab A/C, Lithium battery
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Worktop damage // mirror in rear cracked //



Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No



CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	Seven stamps 2016, 17, 18, 19, 23 & 24
Date of Last Engine Service	24/02/2024
Cam belt changed	No
Habitation service reports	None



Test Drive & Sign Off

Test drive - 10 mins	Pass
----------------------	------

Yes	
Completed by	David Walker
Sign-off Date	2026-09-10