Date Submitted: 09/11/2026 04:55 AM
Submitted By: David Walker

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Japanese Auto Locators Elgrand
Reg Number - NO GAP	VT03BXP
HPI Clear	Yes
VAT	No
Engine Size	3.5
BHP	240
Transmission	Automatic
Vehicle Weight (kg)	2450
Miles or KM	KM
Mileage	36596
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes
MOT Expiry Date	09/09/2027
Vehicle Registration Date	01/09/2023

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

Date Submitted: 09/11/2026 04:55 AM
Submitted By: David Walker

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	N/A
Clutch Slip Test Pass	N/A
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	5
Bed Options	Campervan
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

CMS
AUCTIONS
Browse | Bid | Buy

Date Submitted: 09/11/2026 04:55 AM
Submitted By: David Walker

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Reversing camera, Front fog lights
Other External Extras	N/A
Decals	N/A
Any Damage Found	Yes
Damage Further Info	Cracks on side skirts // dent in drivers door







Windscreen	No damage
Alloy Wheels	Need attention
Alloy Further Info	Chrome rusting



Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	No

Date Submitted: 09/11/2026 04:55 AM
Submitted By: David Walker

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Auto headlights, cab A/C, Climate control, Cruise control, Heated mirrors, Leather, Multifunction steering wheel
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	No

Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	No
Engine Service History	Partial
Service Info	Invoiced 2025
Date of Last Engine Service	09/06/2025
Cam belt changed	N/A
Habitation service reports	None



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	David Walker
Sign-off Date	2026-11-09