

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	JAL Conversions
Reg Number - NO GAP	VU53HNY
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	98
Transmission	Automatic
Vehicle Weight (kg)	2050
Miles or KM	KM
Mileage	67038
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass


CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	N/A
Clutch Slip Test Pass	N/A
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	No
Notes	N/A
Berths	4
Belts	4
Bed Options	Campervan
Lounge Layout	Two Forward Facing
Layout Correct	Yes
Further Comments	N/A




CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Parking sensors, Front fog lights
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Front o/s bumper end small scratch//o/s door mirror paint flaking//o/s roof channel start of corrosion// o/s panel behind door brushing scratch marks//o/s bottom panel dent and poor repair//o/s wheel arch bubbling//front n/s splitter dented//o/s splitter scratches//n/s wheel arch scratches//n/s rear bumper repair dent//n/s roof channel corrosion//sliding door brush scratching and discolouration //rear n/s side wheel arch corrosion//rear n/s quarter panel scratching//corrosion under cill o/s//corrosion under n/s cill//extensive scratching on nearside of pop top/:








Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	Yes
Tyre Further Info	Front o/s tyre cracking// front n/s tyre cracking//






Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	No

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	None
Other Extras	Automatic blinds
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Hook drilled into bulkhead roof//no gas cabinet//stain on rear seat backrest



Damp Inspection

Damp (visible/soft)	No
---------------------	----




CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	Partial
Date of Last Engine Service	15/09/2025
Cam belt changed	No
Habitation service reports	None



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Mark Czechowski
Sign-off Date	2026-09-17

