# CMS MOTORHOME INSPECTION FORM

## General Information

| | |
|---|---|
| Make & Model | Auto-Sleeper Bourton |
| Reg Number - NO GAP | VX20BNE |
| HPI Clear | Yes |
| VAT | No |
| Engine Size | 2143 |
| BHP | 160 |
| Transmission | Automatic |
| Vehicle Weight (kg) | 3500 |
| Miles or KM | Miles |
| Mileage | 7061 |
| Confirm miles (within 5,000) | Yes |
| Is Mileage Warranted | Yes |
| Engine Keys Count | 2 |
| V5 present | Yes |
| V5 VIN Match | Yes |
| MOT Expiry Date | 10/04/2027 |
| Vehicle Registration Date | 01/07/2020 |

## Engine Bay

| | |
|---|---|
| Fluid levels correct? | Yes |
| Oil/Coolant Contamination | No |
| Engine bay check | Pass |

Date Submitted: 06/11/2026 08:12 AM
Submitted By: Alan Wileman

# CMS MOTORHOME INSPECTION FORM

## Mechanical Inspection

| | |
|---|---|
| Brake Pedal Pressure Pass | Yes |
| Handbrake Test Pass | Yes |
| Static Gear Selection Pass | Yes |
| Clutch Slip Test Pass | Yes |
| Steering Noise | No |
| Engine Noise | No |

## Internal Layout

| | |
|---|---|
| Does internal look original? | Yes |
| Berths | 2 |
| Belts | 2 |
| Bed Options | Bench Seats |
| Lounge Layout | Bench Seats |
| Layout Correct | Yes |
| Further Comments | N/A |

# CMS MOTORHOME INSPECTION FORM

## Exterior Inspection

| | |
|---|---|
| External Extras | Awning, Solar panel, Tow bar, Alloys, Reversing camera, LED daytime running lights, Electric step |
| Other External Extras | N/A |
| Decals | Need attention |
| Decals Further Info | Peeling on front |



| | |
|---|---|
| Any Damage Found | Yes |
| Damage Further Info | Oil leak |





| | |
|---|---|
| Windscreen | No damage |
| Alloy Wheels | Good |
| Tyres illegal/cracking/out of date | No |
| Electric Step | Fully Working |
| Self levelling work | N/A |
| Pop top canvas damage | N/A |

**CMS**
AUCTIONS
Browse | Bid | Buy

Date Submitted: 06/11/2026 08:12 AM
Submitted By: Alan Wileman

# CMS MOTORHOME INSPECTION FORM

## Internal Inspection

| | |
|---|---|
| Internal Extras | cab A/C, Bluetooth, Auto wipers, Auto headlights, Cab blinds, Carpets, DAB radio, Cruise control, Habitation A/C, Multifunction steering wheel, Oven, Sat nav, Tv(s), Other (inc accessories) |
| Other Extras | Microwave |
| Electrics turn on | Yes |
| Control panel damaged | No |
| Stereo turn on | Yes |
| Smell or signs of smoking | No |
| Cushions correct | Yes |
| Boiler present | Yes |
| Overhead lockers ready | Yes |
| Internal Damage | Yes |
| Damage Info | Carpet screwed into floor |



## Damp Inspection

| | |
|---|---|
| Damp (visible/soft) | No |
| Floor damp/spongy/damaged | No |



**CMS**
AUCTIONS
Browse | Bid | Buy

Date Submitted: 06/11/2026 08:12 AM
Submitted By: Alan Wileman

# CMS MOTORHOME INSPECTION FORM

## Paperwork

| | |
|---|---|
| Manuals present | Yes |



| | |
|---|---|
| Engine Service History | Partial |
| Service Info | 4 service stamps |
| Date of Last Engine Service | N/A |
| Cam belt changed | No |
| Habitation service reports | Partial |
| Habitation Info | 5 services |
| Date of Last Habitation Service | N/A |






## Test Drive & Sign Off

| | |
|---|---|
| Test drive - 10 mins | Pass |
| Engine lights | No |
| Dashboard ghosting/Mileage flashing | No |
| V5 tested on DVLA | Yes |
| Completed by | Arran Ashman |
| Sign-off Date | 2026-11-06 |