

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Wellhouse Leisure I800
Reg Number - NO GAP	YN14DFC
HPI Clear	Yes
VAT	No
Engine Size	2500
BHP	130
Transmission	Manual
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	22131
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	5
Bed Options	Campervan
Lounge Layout	Two Forward Facing
Layout Correct	Yes
Further Comments	N/A



CMS MOTORHOME INSPECTION FORM


Exterior Inspection

External Extras	Alloys, Front fog lights, Parking sensors, Tow bar, Gaslow
Other External Extras	N/A
Decals	N/A




Any Damage Found	Yes
Damage Further Info	Scuff to bumper Dent to front bumper Mark to rear corner Mark to rear trim Scratch to trim n/s Scuff to front bumper







Windscreen	No damage
Alloy Wheels	Need attention
Alloy Further Info	Scuff to o/s rear



Tyres illegal/cracking/out of date	Yes
Tyre Further Info	No date Showing signs of cracking



Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	Yes
Pop Top Damage Info	Holes in n/s



CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	cab A/C, Carpets, Diesel heater, Draw locking, Heated seats, Multifunction steering wheel, Oven
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	No
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Cracked dash Damage to trim by oven Scuffs to interior door and corner Scuff to passenger seat Delaminating on trim o/s Scuff in boot






Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No



CMS MOTORHOME INSPECTION FORM


Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	11 services last one photographed
Date of Last Engine Service	12/02/2026
Cam belt changed	N/A
Habitation service reports	Partial
Habitation Info	Last one photographed
Date of Last Habitation Service	12/05/2026





Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Arran Ashman
Sign-off Date	2026-09-22